



## Two-point measurement with a single unit

The two pressure sensors measure pressures at two points. Pressure values are obtained through serial communication.

- In-line pressure measurement at up to two points
- Compatible with serial communication
- Pressure sensors available for individual sale



Without cables

### Specifications

Model	FC-PSU-1000
Pressure Range	0–6.0 MPa
Wetted Part Material	PTFE (with the pressure sensor made of SUS316 coated with Teflon)
Connector	1/16" taper seal (No. 10-32UNF)
Power Supply	AC 100-240V 50/60 Hz 30 W